

New in October 2026

Updates

- The updated [Roof Outline](#) design mode, with automated roof detection, is now available on [Easy PV Ireland](#).
- Updated the Renusol hanger bolt options for fibre cement and sheet metal roofs. Steel purlin roofs now use the 150mm hanger bolt only.
- Updated the Fastensol MCS012 data to their latest MCS certificate (MR 50735501).
- Improved how [SolShare](#) handles incompatible hybrid inverters and batteries.
- AC isolators, DC isolators and meters now link to their own [help page](#) from the component editor.
- Team management now shows the date each team was created.

Fixes

- Corrected Solfit parts lists to stop over-specing on multi-roof installs.
- Fixed Solfit bottom flashing options not selecting.
- Fixed optimiser selection for SolarEdge inputs in the Inverter task.
- Fixed hybrid inverters not showing their charge rate and efficiency in the Inverter task.
- Fixed the “switching 2 strings in parallel” option disappearing after choosing a 2-pole DC isolator.
- Whole System Design now explains when a roof is missing an orientation, instead of showing an error.
- Customer details in the navigation bar now update straight away after editing project details from another window.

Revision #1

Created 19 October 2026 14:59:46 by Michael Barbour

Updated 19 October 2026 16:31:13 by Michael Barbour