

# New in January 2026

---

## Updates

- Added the option to **clone inverters** when using multiple of the same type. Stringing is copied by default.
- New **bulk update** options for all **DC isolators and cables** within the electrical task.
- **MCS handover document** added.
- Signature date is now auto-completed when e-signing.
- Improved how **GSE trays** are specified relative to **panel size**. Easy PV will now always select the **minimum compatible size**.
- **BirdBlocker clips** are now specified based on **panel frame width**.
- **Extra BirdBlocker clips** are only specified when required.
- Added way to easily **set up payment** after a **free trial of Easy PV Pro**.
- One **Fastensol L Bracket** is now specced per hook for Fastensol Standing Seam systems, replacing the Fastensol cross connect.

## Fixes

- Fixed issues with east-west mounting and panel allocation.
- Corrected the system overview summary generated in the proposal when both string and hybrid inverters are selected.
- Updated DNO form rounding to 2 decimal places (e.g. 3.68 kW no longer rounds to 3.7 kW).
- Fixed incompatible pan tile hooks being specified for Fastensol and Renusol flat tile roofs.
- Financial task rounding now respects the selected currency rather than defaulting to 1 decimal place.
- Fixed Pro account financial setting rules that weren't working correctly for Admin role and added Owner role.
- Updated MCS012 certificate used in the Structural task for Fastensol pan tile hooks.

---

Revision #7

Created 26 January 2026 11:55:41 by Daisy

Updated 29 April 2026 08:38:29 by Daisy